

FLK
OSA - 3374-64

IN 1955

8 July 1964

STATINTL

To:

From:

Subject: Service Bulletin - HMI - 73B - SB5

1. Since subject bulletin is maintenance information only and is the result of an approved ECP, advance and information copies have been combined herewith for your cognizance and approval for issue. Action copies are being shipped to Denard to await your instruction.

2. To date, "B" Serial Nos. 101, 119, 120, 11 and 12 have been outfitted with the new sensors. Interim maintenance instructions were packed with each modified unit shipped.

STATINTL

AJB:dt
Encl.